



# COMPASS DECISION MANAGEMENT SYSTEM™ INTEGRATION DRIVERS

**ENSURING YOUR OPERATORS PERFORM AT THEIR BEST EVERY TIME**

| PART NUMBER | DRIVER TYPE                     | INTEGRATION DRIVER NAME         | VENDOR SUPPORTED VERSION *   | VENDOR LICENSES REQUIRED |
|-------------|---------------------------------|---------------------------------|--|--------------------------|
| 350100      | Access Control Driver           | Avigilon ACM                    | 5.1 onwards  | Yes                      |
| 350110      | Access Control Driver           | DDS Amadeus 5                   | 3F25+2.4.16 (Microsoft Access Database only)   |                          |
| 350120      | Access Control Driver           | Dorlet                          |  |                          |
| 350150      | Access Control Driver           | Paxton NET2                     | v5.03.52   |                          |
| 350160      | Access Control Driver           | Qontinuum QPSIM/QVIGILA         |  | Yes                      |
| 350170      | Access Control Driver           | Salto                           | 6.1.2.1  | Yes                      |
| 350180      | Access Control Driver           | IDCube                          | v3.2.0.0 Feb 2021  | Yes                      |
| 350190      | Access Control Driver           | Hikvision                       | V1.2.0 Build 210123  | Yes                      |
| 350200      | Access Control Driver           | Assa Abloy Traka                | v3.12.3  | Yes                      |
| 351000      | VoIP Device Driver              | 2N                              | 2.4.1, 2.14.2, 2.8.0.17.2 (bootloader v2.8.0.17.1),<br>2.9.1.18.6 (bootloader v2.8.0.17.1) |                          |
| 351010      | VoIP Device Driver              | Mobotix                         | 2.4.1  |                          |
| 351020      | VoIP Device Driver              | Commend                         | v3.7 Final (Ursus deningeri) Build 143   |                          |
| 352000      | Alarm Panel Driver              | Honeywell Galaxy                | v2.08  |                          |
| 352010      | Alarm Panel Driver              | Honeywell Notifier ID3000       | v4.14 or greater, via Moxa NPort 5510 (v2.8 Build 17090114)                                |                          |
| 352020      | Alarm Panel Driver              | UTC ATS 2021                    | Release ATS1809-00.06.15 Wed Oct 3 11:14:04 CEST 2012                                      |                          |
| 352030      | Alarm Panel Driver              | Satel Integra 256 Plus          | 1.13 20150314  |                          |
| 352040      | Alarm Panel Driver              | Risco LightSyst 2 / ProSys Plus | V01.02.00.0007   |                          |
| 352050      | Alarm Panel Driver              | INIM SmartLiving                | 6.03   |                          |
| 352060      | Alarm Panel Driver              | UTC FP1200/2000                 |  |                          |
| 352070      | Alarm Panel Driver              | TRIKDIS IPcom                   | 4.9.0.3  |                          |
| 352080      | Alarm Panel Driver              | UTC Aritech 2X                  | Panel firmware version: 3.6  |                          |
| 352090      | Alarm Panel Driver              | Bosch D9412/9512 GV4            | 2.03.018   |                          |
| 352100      | Alarm Receivers & Panels Driver | Honeywell Galaxy via Emizon TCD | userapp j.9.8  |                          |

| PART NUMBER | DRIVER TYPE                | INTEGRATION DRIVER NAME                | VENDOR SUPPORTED VERSION *   | VENDOR LICENSES REQUIRED |
|-------------|----------------------------|--|--|--------------------------|
| 352110      | Alarm Panel Driver         | AGORA Alarm Panel Driver: Emizon TCD   |  |                          |
| 352120      | Alarm Panel Driver         | CommBox FogCenter                      | Nevoa API 1.0.0  |                          |
| 352130      | Alarm Panel Driver         | DSC                                    |  |                          |
| 352140      | Alarm Receiver Driver      | Honeywell TCP/IP Receiver              |  |                          |
| 353000      | Building Automation Driver | Moxa ioLogik E1200                     | 1.1  |                          |
| 354000      | Video Driver               | ONVIF S/G Compliant Source             |  |                          |
| 354010      | Video Driver               | RTSP Compliant Source                  |  |                          |
| 354030      | Video Driver               | Axis Cameras                           | 4.49.1; 5.x  |                          |
| 354040      | Video Driver               | Bosch VRM                              | 3.71.029   |                          |
| 354050      | Video Driver               | Bosch Hybrid 3000 Recorders            | 1.3  |                          |
| 354060      | Video Driver               | Dahua Recorders                        | 3.210.00005.0  |                          |
| 354070      | Video Driver               | Ganz DR16H Recorders                   | 14310.1.1345.32  |                          |
| 354080      | Video Driver               | Geutebrück G-Scope/re_Porter Recorders | GeViSoft 5.0.128.3 - gsc 7.6.972.18                                |                          |
| 354090      | Video Driver               | Hikvision Recorders                    | 3.0.15 build 151230  |                          |
| 354100      | Video Driver               | Intelbras Recorders                    |  |                          |
| 354120      | Video Driver               | Provision Recorders                    | 1.0.3 Build20161223, 1.0.4.1R5,B170320E.0.D01.U2(4A41A)            |                          |
| 354130      | Video Driver               | Lanaccess OnSafe Recorders             | 8.9.31   |                          |
| 354140      | Video Driver               | Milestone VMS                          | 10.0a  | Yes                      |
| 354150      | Video Driver               | Mobotix Cameras                        |  |                          |
| 354160      | Video Driver               | Avigilon ACC                           | ACC versions 6 and 7, tested with Web Endpoint API version 7.6.2.2 |                          |
| 354170      | Video Driver               | IndigoVision Control Center            | v16 onwards  |                          |
| 354180      | Video Driver               | IndigoVision Cameras                   |  |                          |
| 354190      | Video Driver               | IndigoVision Kiosk AI                  |  |                          |
| 354200      | Video Driver               | Ganz Cortrol VMS                       | 1.18.1   |                          |
| 354210      | Video Driver               | Pelco VideoXPert                       | 3.0.154  |                          |

\* The existing Compass Integration Driver was developed and tested using this vendor version; For other vendor versions please contact your Regional Sales Engineer.

For more information, please visit [www.motorolasolutions.com/compass](http://www.motorolasolutions.com/compass)



Motorola Solutions Ltd. Nova South, 160 Victoria Street, London, SW1E 5LB, UK. [motorolasolutions.com](http://motorolasolutions.com)

MOTOROLA, MOTO, MOTOROLA SOLUTIONS and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2021 Motorola Solutions, Inc. All rights reserved. 07-2021