

RECOMMENDED SOLUTIONS FOR RESORTS AND GOLF CLUBS

DIGITAL RADIO PORTFOLIO

MOTO TRBO [™]											
	DEP450	SL500	SL8550e	DEP550e	DEP570e	DGP5050e	DGP5550e	DGP8050e	DGP8050e Elite	DGP8550e	DGM8500e
Guest Relations			✓	✓	✓	✓	✓	✓	✓	✓	
Maintenance and Facilities			✓	✓	✓	✓	✓	✓	✓	✓	✓
Security			✓	✓	✓	✓	✓	✓	✓	✓	✓
Cleaning and Housekeeping			✓	✓	✓	✓	✓	✓	✓	✓	✓
Food and Beverages			✓	✓	✓	✓	✓	✓	✓	✓	✓
Golf Course			✓	✓	✓	✓	✓	✓	✓	✓	
Events and Conventions			✓	✓	✓	✓	✓	✓	✓	✓	
Reception	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
General Management			✓	✓	✓	✓	✓	✓	✓	✓	
RECOMMENDED SYSTEMS 						CAPACITY MAX					
	IP SITE CONNECT			SINGLE-SITE CAPACITY PLUS			MULTI-SITE CAPACITY PLUS				
	CONVENTIONAL										

ADD THE RIGHT ACCESSORY

EARPHONES AND HEADPHONES	WIRELESS BLUETOOTH FOR MOBILE AND PORTABLE RADIOS	BATTERIES AND CHARGERS	MICROPHONES	CLIPS

WITH SOME OF THESE DEVICES, YOU CAN GET THE FOLLOWING OPTIONS:

FUNCTIONALITIES

Voice Scrambling	Active or Inactive Radio Report	Text to Speech	Noise Cancellation	Voice Announcement	Intelligent Audio
Remote Monitoring	Emergency Button	Vibrating Alert	Selective Calling	Covert Mode	Lone Worker
Communications Log	Evidence of Radio Location	Call Interruption for Emergencies			

APPLICATIONS

Work Orders	Dispatch Consoles	Text Messages	Network Monitoring	Radio on Your Cell Phone	Telemetry
Telephony	Lone Worker	Indoor Positioning	Email	Integrated Bluetooth	Personnel Management
Communications Recording	Alarm Control and Notification	Interoperability	Man-Down Applications		

RESISTANCE

Water Resistant	Impact Resistant	Heat Resistant	Cold Resistant	Dust Resistant	Intrinsically Safe
-----------------	------------------	----------------	----------------	----------------	--------------------

Repeater antennas are placed between different locations and/or linked via a network connection.



BETTER COMMUNICATION BETWEEN AREAS IMPROVES EXPERIENCE. THE RESULT: **HAPPY GUESTS AND SATISFIED EMPLOYEES.**

PHONE NUMBERS FOR LATIN AMERICA AND THE CARIBBEAN

Argentina (Buenos Aires) +54 11 5168 5775
Brazil (São Paulo) +55 11 4230 0151
Chile (Santiago) +56 2 2582 1173

Peru (Lima) +51 1706 8493
Uruguay (Montevideo) +917 477 0577

Colombia (Bogota) +57 1508 7063
Costa Rica (San Jose) +506 4010 0514

Mexico (Mexico City) +52 55 4160 7913
Venezuela (Caracas) +58 212 720 4391

Write to:
valeria.garcia1@motorolasolutions.com

Write to:
juan.choa@motorolasolutions.com

https://www.motorolasolutions.com/en_us/solutions/hospitality.html

